



**GOVERNMENT OF KHYBER PAKHTUNKHWA
FORESTRY, ENVIRONMENT AND WILDLIFE DEPARTMENT**

Details of Rest Houses of Forest Department

1. CENTRAL SOUTHERN FOREST REGION-I

S.No.	Forest Inspection Hut	Location	Year of construction	No. of room	No. of wash rooms	Total area (sqft)	Covered area (sqft)	Present use	Up-gradation / revision	Remarks
1	Toi Banda	Toi Banda near Khushalgarh on the bank of Indus River	1974-75	Bed room = 2 Hall = 1	2	10890 Sq. Ft.	1905.75 Sq. Ft.	In working condition	3.81M	-



**GOVERNMENT OF KHYBER PAKHTUNKHWA
FORESTRY, ENVIRONMENT AND WILDLIFE DEPARTMENT**

2. NORTHERN FOREST REGION-II ABBOTTABAD

#	Forest Division and District	Forest Inspection Hut Name	Location	Year of construction	No. of Rooms	No. of Wash Rooms	Total Area (sft)	Covered Area (sft)	Present use	Up-gradation / Renovation cost (Rs. in millions)	Remarks
1	Haripur Forest Division, District Haripur	Khanpur	Khanpur	1980-81	04	02	2700	2700	The Officers/ Officials of Forest Department are using Forest Inspection Hut during their field visit.	4.05	Good condition
2		Jabri	Jabri	1908-09	02	02	1547	1547		2.32	Good condition
3		Makhnial	Makhnial	1922-23	02	02	1525	1525		2.28	Good condition
4		Mari	Mari	1907-08	02	0	1046	1046		1.56	Not fit for living
5	Gallies Forest Division	Thandiani	Thandiani Top	1922	03	04	9938	2189	Transferred to Tourism Corporation	-	Good condition
6	Abbottabad, District Abbottabad	(Press Cottage)Nathial	MochiDhara	1921	03	03	16320	2260	KPK vide Notification	-	Good condition



**GOVERNMENT OF KHYBER PAKHTUNKHWA
FORESTRY, ENVIRONMENT AND WILDLIFE DEPARTMENT**

7		Barrian	Barrian	1907	04	04	6500	2300	No.SO(Admin)/Misc/2015 dated 26.6.2015	-	Good condition
8		Dagri	Dagri	1899	03	03	11016	9792	Gallies Forest division	29.0	Demolished
9		Sattu	Sattu Tarnwai	1902	03	01	11157	3599	Gallies Forest division	10.79	Worse condition
10		Birangali	Birangali	1923	04	04	8280	3174	Gallies Forest division	-	Under constructions by ERRA
11	Kaghan Forest Division Jabba, District Mansehra	Shogran	Shogran	2002-03	05	05	28016	7477	V/Good	0.2	Most of the Forest Rest Houses/ inspection Hut were constructed since 1955-56 which were being used by local protective staff as well as by the officers during field visit to respective Forest areas.
12		Hill top	Shogran	1992-93	02	02	-	2200	Good	0.300	
13		Shinkiari	Sangar	1968-69	02	02	-	2500	V/Poor	3.75	
14		Kaghan	Kaghan	1985-86	02	02	5440	750	Satisfactory	1.12	



**GOVERNMENT OF KHYBER PAKHTUNKHWA
FORESTRY, ENVIRONMENT AND WILDLIFE DEPARTMENT**

#	Forest Division and District	Forest Inspection Hut Name	Location	Year of construction	No. of Rooms	No. of Wash Rooms	Total Area (sft)	Covered Area (sft)	Present use	Up-gradation / Renovation cost (Rs. in million)	Remarks
15	Kaghan Forest Division Jabba, District	Walnut Inspection Hut Naran	Naran	1989-90	02	02	21760	800	Satisfactory	1.20	Most of the Forest Rest Houses/inspection Hut were constructed since 1955-56 which were being used by local protective staff as well as by the officers during field visit to respective Forest areas.
16	Mansehra	Naran New	Naran	1981-82	02	02	5440	1550	Poor	3.10	
17		Naran old	(Pine)Naran	1955-56	02	02	5440	1121	V/Poor	3.36	
18		Saif-ul-malook	Saif-ul-malook lake	1955-56	02	02	2720	900	V/Poor	2.70	
19		Kamalban	Kamalban	1997-98	02	02	8160	1857	Poor	3.71	
20		Biari	Manoor	1989-90	02	02	16320	1800	Satisfactory	2.70	
21		Lalian Danna	Lalian Danna	1989-90	02	02	16320	600	Poor	1.20	
22		Serian	Serian	1981-82	02	02	5440	780	Satisfactory	1.17	
23		Seri	Seri	1960-61	02	02	10880	1000	Poor	2.00	
24		Naddi	Naddi	2017-18	02	02	2096	2096	Under construction through (SFM)	0.200	
25		Paprang	Paprang	1988-89	02	02	5440	5400	Collapsed	16.20	



**GOVERNMENT OF KHYBER PAKHTUNKHWA
FORESTRY, ENVIRONMENT AND WILDLIFE DEPARTMENT**

									during earthquake Oct 2005		
26		German House Malkandi	Malkandi	-	02	02	--	3000	Collapsed during earthquake Oct 2005	9.00	The building constructed by GTZ therefore the record of cost/date of construction is not available on the record of this office
27		Mohandri	Mohandri	1991-92	02	02	21760	2500	Collapsed during earthquake Oct 2005	7.50	-



**GOVERNMENT OF KHYBER PAKHTUNKHWA
FORESTRY, ENVIRONMENT AND WILDLIFE DEPARTMENT**

#	Forest Division and District	Forest Inspection Hut Name	Location	Year of construction	No. of Rooms	No. of Wash Rooms	Total Area (sft)	Covered Area (sft)	Present use	Up-gradation / Renovation cost (Rs. in million)	Remarks
28	Siran Forest Division Mansehra, District Mansehra	Dadar	Dadar	1933	06	04	26950	2430	The Officers/ Officials of Forest Department are using Forest Inspection Hut during their field visit.	2.43	Good condition. In addition to existing building, the ERRA has reconstructed separate building at each location. The completion status of which is 70% and 60% respectively.
29		Domel	Domel	1933	04	03	21780	2430		2.43	
30		Shaheed Pani	Shaheed Pani	Under reconstruction by ERRA.			5440	2430		-	
31		KundBunglow	Kund Bunglow				5440	2430	-	3.000	Demolished



**GOVERNMENT OF KHYBER PAKHTUNKHWA
FORESTRY, ENVIRONMENT AND WILDLIFE DEPARTMENT**

32	Agror Tanawal	Karori	Karori Shergarh	2008-09	04	02	6800	1700	Not handed over to Deptt. by ERRRA	2.000	Under reconstruction by ERRRA.	
33	Forest Division,	Hawagali	Hawagali Agror	2008-09	04	02	10880	3150	Not handed over to Deptt. by ERRRA	2.000		
34	District Mansehra	Doga	Doga Shergarh	2010-11	02	02	2720	1600	The Officers/ Officials of Forest Department are using Forest Inspection Hut during their field visit	2.40		Living condition
35	Hazara Tribal	Gangwal	Allai	Gangwal	2007-08	05	05	16320	1500	Demolished during earthquake 2005	2.500	Under reconstruction through ERRRA
36	Forest Division, District Battagram	Bateela	Allai	Bateela	2007-08	05	05	18768	1500		2.500	

#	Forest Division and District	Forest Inspection Hut Name	Location	Year of construction	No. of Rooms	No. of Wash Rooms	Total Area (sft)	Covered Area (sft)	Present use	Up- gradation / Renovation cost (Rs. in million)	Remarks
37	Hazara Tribal	Dabbri Battagram	Dabbri	2007-08	02	01	5440	667	The Officers/ Officials of Forest Department are using Forest Inspection Hut during	1.000	Good condition
38	Forest Division,	Kathora Hillan	Kathora	2007-08	02	01	5440	667		1.000	Good condition



**GOVERNMENT OF KHYBER PAKHTUNKHWA
FORESTRY, ENVIRONMENT AND WILDLIFE DEPARTMENT**

	District								their field visit.		
39	Battagram	Shakhel Hillan	Shakhel	2007-08	02	01	5440	667		1.000	Good condition
40	Lower	Sherakot	Palas	2011-2012	02	02	-	1634	Not fit for living	4.90	Bad Condition
41	Kohistan Forest	Chakai at Sholgara.	Pattan	2007-08	02	02	-	2178	Not fit for living	3.26	Satisfactory Condition
42	Division,	Keyal	Pattan	1972	-	-	-	-	Not fit for living	6.000	Completely washed away during flood 2010
43	District Pattan	Dubair	Pattan	1974	-	-	-	-	Not fit for living	7.000	
44	Upper	Dassu	Dassu	1982-83	03	03	3264	2176	The Officers/ Officials of Forest Department are using Forest Inspection Hut during their field visit.	1.00	Basically the Forest Rest Houses/ inspection huts was constructed for living of protective staff, the transfer of inspection huts will creates problems for field staff and they will become shelter less.
45	Kohistan Forest Division, District Dassu	Shatial	Shatial	1982-83	03	03	3264	2176		1.00	



**GOVERNMENT OF KHYBER PAKHTUNKHWA
FORESTRY, ENVIRONMENT AND WILDLIFE DEPARTMENT**

Note:

These are Forest Inspection Huts, which are situated at the places where there is no alternative accommodation for visiting of forest officers. Due to low accommodation capacity, running these Forest Inspection Huts as commercial enterprise would not be cost effective. Due to wilderness of the area, high security arrangements have to be afforded by the concerned agency if used for renting to tourist. Further the high operational charges will necessitate high rental charges whereby the middle class will be excluded state away.

3. MALAKAND FOREST REGION-III

S.No	Forest Inspection Hut	Location	Year of construction	No. of room	No. of washrooms	Total area (sqft)	Covered area (sqft)	Present use	Up-gradation / revision (Rs. In Million)	Remarks
1	Camp House Shagai	Urban – Saidu Sharif	1990	Rooms = 03 Hall = 01 Kitchen = 01	03	6528 Sq.Ft	6528 Sq.Ft	--	1.000	--
2	Karaker	Rural – Barikot	Re-constructed during 2015-16	Rooms = 02	01	10200 Sq.Ft	3808 Sq.Ft	--	4.000	--



**GOVERNMENT OF KHYBER PAKHTUNKHWA
FORESTRY, ENVIRONMENT AND WILDLIFE DEPARTMENT**

		Valley Karkar top								
3	Lalku	Lalku Valley at Garrai	1996	Rooms = 03 Hall = 01 Kitchen = 01	03	10000 Sq.Ft	2500 Sq.Ft	--	5.000	--
4	Behrain	Behrain	Constructed during the regine of Wali Swat	Rooms = 02 Drawin g Room = 01 Dinning Hall = 01 Smal Room = 1 Kitchen = 01	3	4 Kanal (21780) Sq. Ft	2217 Sq. Ft	--	3.32	Needs miner repair
5	Kulalai	Behrain	-- do --	-- Nil --	-- Nil --	6 Kanal (32670) Sq. Ft	--	--	--	Washed away in flod 2010
6	Banr	Kalam	0	Rooms = 02 Drawin g Room = 01 Dinning	2	15 Kanal (81675) Sq. Ft	3941 Sq. Ft	--	7.88	Dilapidafed needs major reparir as scriously damage by wind fallen



**GOVERNMENT OF KHYBER PAKHTUNKHWA
FORESTRY, ENVIRONMENT AND WILDLIFE DEPARTMENT**

				Hall = 01 Kitchen = 01							tree
--	--	--	--	---------------------------------	--	--	--	--	--	--	------

7	Utrol -I	Utrol	0	Rooms = 02 Danning Hall = 01 Chowk: Hut = 1	2	2 Kanal (10890) Sq. Ft	5445 Sq. Ft	--	2.00	--	Needs miner repair
8	Utrol -II	Utrol	0	Rooms = 02 Danning Hall = 01	2	2 Kanal (10890) Sq. Ft	2 Kanal	--	1.5	--	---
9	Matiltan	Matiltan	0	Rooms = 02 Hall = 01 D Hall = 01 Kitchen = 01		8 Kanal	8 Kanal	--	3.00	--	Needs Construction boundary wall renovation and Specially the serve water problems
10	Bayun	Bayun Kham	1993-94	Rooms = 3 Drawing room = 01 Kitchen = 01 store = 01	2	2 Kanal (10890) Sq. Ft	5445 Sq. Ft	--	10.89	--	Dilapidated needs major repair



**GOVERNMENT OF KHYBER PAKHTUNKHWA
FORESTRY, ENVIRONMENT AND WILDLIFE DEPARTMENT**

11	Shangla	Shangla top	1988	9 rooms and 1 hall	4 washrooms	7 kanals 11 marlas	2000 sft	--	2.00	--	--
12	Yakhtangay	Yakhtangay top	since 2005	4 rooms and 1 hall	3 washrooms	8 kanal 14 marlas	1280 sft	--	1.00	--	--
13	Opal Kandao	Kandao top opal	since 2005	4 rooms and 1 hall	3 washrooms	4933 sft	1280 sft	--	1.00	--	--
14	Ajmir	AjmirShahpur	1996	3 rooms and 1 hall	3 washrooms	1 Kanal	1280 sft	--	1.00	--	--
Malakand West Forest Circle:											
1	Laram	Lower Dir	2005	02	02	297297	774	serviceable	2		
2	Kass	Upper Dir	1994	03	03	16320	5440	Unserviceable	16.32		
3	Battal	Upper Dir	1994	03	03	10880	5440	do	16.32		
4	Kumrat	Dir-Kohistan	1992	03	03	13612.5	2367	In use of Pak Army	01		
5	Badogai	Dir-Kohistan	2007	04	03	150635.5	2376	Forest Deptt	02		
6	Thall	Dir-Kohistan	1974	03	03	5445	2367	Unserviceable	7.10		Transfer from C&W Dept in 1975
7	Kalkot	Dir-Kohistan	1974	02	01	2722.5	792	Unserviceable	2.37		-do-
8	Bumborit	Chitral	1989-90	02	02	10890	500	Serviceable	0.75		
9	Danin Camp office	Chitral	1992-96	02	02	10890	1980	Service-able	2.97		
10	Drosh Camp office	Chitral	1972-73	03	02	10890	1713	Service-able	2.56		